



9 Pineside Road, New Germany 3610

ISO 14001 COMPLIANT

# Safety Data Sheet

PAGE 1 OF 11

SDS 0216/161

# 1. IDENTIFICATION OF THE SUBSTANCE / MIXTURE AND OF THE COMPANY

# Product Identifier

Product Description:

# **POLYLITE 33282-00**

#### Other Means of Identification:

Sage Code: P3328200------K000 Chemical Family: Polyester Resin

# Recommended use of the chemical and restrictions on use:Intended use:Infusion resinUses advised against:No information available.

# Details of the supplier of the Safety Data Sheet

Manufacturer / Supplier		
Durban Head Office	TEL	031 713 0600
	FAX	031 705 9858
EMERGENCY TELEPHONE No.	:	031 713 0600

# Supplier

Aurora Glass Fibre NZ Ltd	TEL	+64 9 273-3540	3/16 Zelanian Drive, East Tamaki
	FAX	+64 9 273-3565	Auckland 2013, New Zealand

# 2. HAZARDS IDENTIFICATION

### **Classification**

GHS Classification Health

Acute toxicity - Dermal Category 4 Acute toxicity - Inhalation (Vapors) Category 4 Skin corrosion/irritation Category 2 Serious eye damage/eye irritation Category 2A Carcinogenicity Sub-category 1B Specific target organ toxicity (single exposure) Category 3 Specific target organ toxicity (repeated exposure) Category 1

Environmental

Chronic aquatic toxicity Category 3





# Safety Data Sheet

PAGE 2 OF 11

SDS 0216/161

#### Physical

Flammability - Hazard category 3 Flammable liquid and vapour

#### GHS Labels / Pictograms



#### **Emergency Overview Statements**

Danger

Hazard Statements Harmful if inhaled Causes skin irritation Causes serious eye irritation May cause cancer May cause respiratory irritation Causes damage to hearing through prolonged or repeated exposure if inhaled Harmful to aquatic life with long lasting effects Flammable liquid and vapor

#### **Precautionary Statements - Prevention**

Obtain special instructions before use Do not handle until all safety precautions have been read and understood Use personal protective equipment as required Use only outdoors or in a well-ventilated area Wash face, hands and any exposed skin thoroughly after handling Wear protective gloves/protective clothing/eye protection/face protection Do not breathe mist, vapors, spray Do not eat, drink or smoke when using this product Keep away from heat/sparks/open flames/hot surfaces. - No smoking Keep container tightly closed Ground/bond container and receiving equipment Use explosion-proof electrical/ventilating/lighting equipment Use only non-sparking tools Take precautionary measures against static discharge Keep cool Avoid release to the environment Contaminated work clothing should not be allowed out of the workplace





# Safety Data Sheet

PAGE 3 OF 11

SDS 0216/161

#### **Precautionary Statements - Response**

IF exposed or concerned: Get medical advice/attention

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing If eye irritation persists: Get medical advice/attention

If skin irritation occurs: Get medical advice/attention

IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower

Wash contaminated clothing before reuse

If skin irritation or rash occurs: Get medical advice/attention

IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing

In CASE OF FIRE: Use CO2, dry chemical, or foam to extinguish

#### **Precautionary Statements - Storage**

Store in a well-ventilated place. Keep container tightly closed

#### **Precautionary Statements - Disposal**

Do not discharge into lakes, streams, ponds and ground water supply.Dispose of in accordance with local statutory regulations

#### Hazards not otherwise classified (HNOC)

#### Other Information

Unknown acute toxicity 66.0% of the mixture consists of ingredient(s) of unknown toxicity. Unknown aquatic toxicity 66.7% of the mixture consists of components(s) of unknown hazards to the aquatic environment.

# 3. COMPOSITION/ INFORMATION ON INGREDIENTS

Component	CAS No	Weight %
Polyester Resin	Proprietary	59.5
Styrene	100-42-5	38.3
Alpha- Methyl Styrene	98-83-9	1 - 2
Cobalt compounds	Proprietary	<0.15

### 4. FIRST - AID MEASURES

First Aid Measures	
Eye Contact	Immediately flush eyes for at least 15 minutes. Get medical attention.
Skin Contact	Wash off with warm water and soap. Remove contaminated clothing and shoes. If skin irritation persists, call a physician. Wash contaminated clothing before reuse.
Inhalation	Remove person to fresh air. If signs/symptoms continue, get medical attention. Keep patient warm and at rest. If not breathing, give artificial respiration. If breathing is labored, administer oxygen. Get medical attention immediately.
Ingestion	Do not induce vomiting. Potential for aspiration if swallowed. This material may enter the lungs during vomiting. Never give anything by mouth to an unconscious person. GET IMMEDIATE MEDICAL ATTENTION.





# Safety Data Sheet

PAGE 4 OF 11

SDS 0216/161

#### Most important symptoms and effects, both acute and delayed

Most Important Symptoms No information available and Effects.

#### Indication of any immediate medical attention and special treatment needed

Notes to Physician Treat symptomatically.

### 5. FIRE - FIGHTING MEASURES

#### Suitable Extinguishing Media

Carbon dioxide (CO2), Foam, Dry chemical, Water spray

#### Unsuitable Extinguishing Media

Do not use a solid water stream as it may scatter and spread fire.

#### Specific hazards arising from the chemical

Hazardous combustion products	Combustion may produce carbon monoxide, carbon dioxide and irritating or toxic vapors
	and gases
Combustion/Explosion Hazards	Flammable. Vapors may form explosive mixture with air. Flash back possible over
	considerable distance. This material may polymerize (react) when its container is exposed
	to heat (as during a fire). This polymerization increases pressure inside a closed container
	and may result in the violent rupture of the container. Empty containers may retain product
	residue (liquid and/or vapor). Do not pressurize, cut, weld, braze, solder, drill, grind, or
	expose these containers to heat, flame, sparks, static electricity, or other sources of ignition
	as the container may explode and may cause injury or death.

#### **Protective Equipment and Precautions for Firefighters:**

Wear self-contained breathing apparatus (SCBA) and full fire-fighting protective clothing. Thoroughly decontaminate all protective equipment after use. Evacuate all persons from the fire area to a safe location. Move non-burning material, as feasible, to a safe location as soon as possible. Fire fighters should be protected from potential explosion hazard while extinguishing the blaze. DO NOT extinguish a fire resulting from the flow of this flammable liquid until the flow of liquid is effectively shut off. This precaution will help prevent the accumulation of an explosive vapor-air mixture after the initial fire is extinguished. Use water spray to cool fire-exposed containers.

### 6. ACCIDENTAL RELEASE MEASURES

#### Personal precautions, protective equipment and emergency procedures

Personal Precautions	Remove all sources of ignition. Evacuate personnel to safe areas. Avoid contact with skin and eyes. Use personal protective equipment as required. Ensure adequate ventilation. Keep people away from and upwind of spill/leak. Beware of vapors accumulating to form explosive concentrations. Vapors can accumulate in low areas.
Other Information	All equipment used when handling the product must be grounded.





# Safety Data Sheet

PAGE 5 OF 11

SDS 0216/161

#### **Environmental Precautions**

**Environmental Precautions** Prevent further leakage or spillage if safe to do so. Do not allow material to contaminate ground water system. Prevent product from entering drains. Soak up with inert absorbent material and dispose of as hazardous waste. Beware of vapors accumulating to form explosive concentrations. Vapors can accumulate in low areas.

Methods and material for containment and cleaning up

Methods for Containment Prevent spilled material from 1) contaminating soil, 2) entering sanitary sewers, storm sewers, and drainage systems, and 3) entering bodies of water or ditches that lead to waterways. Prevent spreading over a wide area (e.g. by containment or oil barriers).

Methods for Clean-up Soak up with inert absorbent material. Remove from surface water (e.g. by skimming or siphoning). Dispose of contaminated material as waste according to item 13.

# 7. HANDLING AND STORAGE

#### **Precautions for Safe Handling**

Handling

Storage

Do not breathe vapor or mist. Avoid contact with eyes, skin and clothing. Take off contaminated clothing and wash before reuse. Ensure adequate ventilation. Ground and bond containers when transferring material. Use spark-proof tools and explosion-proof equipment. Consult your supplier of promoters and catalysts for additional instructions on proper mixing and usage. Empty containers may retain product residue (liquid and/or vapor). Do not pressurize, cut, weld, braze, solder, drill, grind, or expose these containers to heat, flame, sparks, static electricity, or other sources of ignition as the container may explode and may cause injury or death. Empty drums should be completely drained and properly bunged. Empty drums should be promptly returned to a drum reconditioner or properly disposed. Do not use compressed air for filling, discharging or handling. Wash hands before breaks and immediately after handling the product.

#### Conditions for safe storage, including any incompatibilities

Keep away from heat and sources of ignition. No smoking. Keep away from direct sunlight. Keep containers tightly closed in a cool, well-ventilated place. To ensure maximum stability and maintain optimum resin properties, resins should be stored in closed containers at temperatures below 77°F (25°C).





# Safety Data Sheet

PAGE 6 OF 11

SDS 0216/161

# 8. EXPOSURE CONTROLS / PERSONAL PROTECTION

#### **Occupational Exposure Limits:**

Components with workplace control parameters Styrene (CAS #: 100-42-5)

Occupational Health and Safety Act, 1993 Regulations for Hazardous Chemical Substances, 1995 Table 1.

> TWA OEL CL 100 ppm (styrene) STEL OEL CL 200ppm

#### Legend

TWA -Time-weighted average STEL - Short Term Exposure Limit OEL - Occupational Exposure Limit Appropriate engineering controls

**Engineering Controls** Use general ventilation to maintain airborne concentrations to levels that are below regulatory and recommended occupational exposure limits. Local ventilation may be required during certain operations. Use explosion-proof equipment.

#### Individual protection measures, such as personal protective equipment

- Eye/face Protection
  Safety glasses with side-shields. If splashes are likely to occur:. Tight sealing safety goggles. Ensure that eyewash stations and safety showers are close to the workstation location. Wear protective nitrile rubber or Viton™ gloves. Gloves made of nitrile rubber or polyvinyl chloride (PVC) may be used for splash protection and brief or intermittent contact with styrenated polyester resin. Please observe the instructions regarding permeability and breakthrough time which are provided by the supplier of the gloves. Also take into consideration the specific local conditions under which the product is used, such as the danger of cuts, abrasion. Impervious clothing. Rubber or plastic boots.
  Respiratory Protection
  None required if hazards have been assessed and airborne concentrations are maintained below the exposure limits listed in Section 8. Wear an approved air-purifying respirator with organic vapor cartridges and particulate filters where airborne concentrations may exceed exposure limits in
  - cartridges and particulate filters where airborne concentrations may exceed exposure limits in Section 8 and/or there is exposure to dust or mists due to sanding, grinding, cutting, or spraying. Use an approved positive-pressure air-supplied respirator with emergency escape provisions if there is any potential for an uncontrolled release, airborne concentrations are not known, or any other circumstances where air-purifying respirators may not provide adequate protection

General Hygiene Considerations Handle in accordance with good industrial hygiene and safety practice.





# Safety Data Sheet

PAGE 7 OF 11

SDS 0216/161

#### 9.

### PHYSICAL AND CHEMICAL PROPERTIES

Appearance Amber Odor Pungent **Odor Threshold** 0.2 ppm (Styrene) **Physical State** Liquid pH Not applicable Flash Point 32 °C / 89 °F Flash Point Method Seta closed cup Autoignition Temperature 490°C / 914°F (Styrene) Boiling point / boiling range 146°C / 295°F (Styrene) Melting point / Freezing point No information available Flammability Limit in Air Lower 1.1% (Styrene) Upper 6.1% (Styrene) 1.09 - 1.10 @ 25°C **Specific Gravity** Solubility Insoluble (Water) **Evaporation Rate** 0.49 (BuAc = 1) (Styrene) Vapor Pressure 5 mmHg @ 20°C (Styrene) 6.7 hPa (Styrene) Vapor Density 3.6 (Air = 1) (Styrene) **Explosive Properties** No information available **Oxidizing Properties** No information available Percent Volatile, wt.% 40 - 50 % by weight 364 g/l (calculated) product as supplied **VOC Content:** 1000 - 14000 cps @ 25°C Viscosity Decomposition temperature No information available

### 10. STABILITY AND REACTIVITY

#### **Reactivity**

No dangerous reaction known under conditions of normal use.

#### **Chemical Stability**

Stable under normal conditions. Stable under recommended storage conditions.

#### Possibility of Hazardous Reactions

Hazardous Polymerization Polymerization ca metal salts and polymerization ca

Polymerization can occur. Hazardous polymerization will occur if contaminated with peroxides, metal salts and polymerization catalysts. Hazardous polymerization may occur upon depletion of inhibitor - may cause heat and pressure build-up in closed containers. Product will undergo hazardous polymerization at temperatures above 65° C.

#### Conditions to Avoid

Heat, flames and sparks. Contamination by those materials referred to under Incompatible materials. Unstable upon depletion of inhibitor. Elevated temperatures.

#### **Incompatible materials**

Strong acids. Strong oxidizing agents. Metal salts. Polymerization catalysts.





# Safety Data Sheet

PAGE 8 OF 11

SDS 0216/161

#### Hazardous Decomposition Products

Hydrocarbons. Carbon monoxide. Carbon dioxide (CO2). Thermal decomposition can lead to release of irritating and toxic gases and vapors.

### 11. TOXICOLOGICAL INFORMATION

#### Information on likely routes of exposure

Primary Routes of Entry Eye contact, Ingestion, Inhalation, Skin Contact, Skin absorption

Acute toxicity

Symptoms

Styrene	
Oral LD50	= 5000 mg/kg (Rat)
Dermal LD50	> 2000 mg/kg (Rat)
Inhalation LC50	= 11.8 mg/l (4 H) (Rat)

#### Information on toxicological effects

Symptoms of overexposure may be headache, dizziness, tiredness, nausea and vomiting.

#### Delayed and immediate effects as well as chronic effects from short and long-term exposure

Eyes	Irritating to eyes.
Skin	Harmful by skin absorption. Contact causes skin irritation. Prolonged skin contact may defat the skin and produce dermatitis.
Inhalation	Harmful by inhalation. May cause irritation of respiratory tract. Inhalation of high vapor concentrations can cause CNS-depression and narcosis.
Ingestion	Harmful if swallowed. Ingestion may cause gastrointestinal irritation, nausea, vomiting and diarrhea. Aspiration hazard if swallowed - can enter lungs and cause damage. Ingestion is not an anticipated route of exposure for this material in industrial use.
Sensitization Not sensitiz	zing.
Repeated dose toxicity	In humans, styrene may cause a transient decrease in color discrimination and effects on hearing. Repeated or prolonged exposure may cause skin irritation and dermatitis, due to defatting properties of the product. May cause damage to the liver, eyes, brain, respiratory system, central nervous system through prolonged or repeated exposure if inhaled. May cause damage to the kidneys, liver, eyes, brain, respiratory system, central nervous system through prolonged or repeated exposure if inhaled.
Mutagenic effects	Styrene has given mixed positive and negative results in a number of mutagenicity tests. Styrene was not mutagenic without metabolic activation but gave negative and positive mutagenic results with metabolic activation.
Carcinogenicity . <u>Styrene</u>	
ACGIH IARC NTP	Group A4 - Not classifiable as a human carcinogen. Group 2B - Possibly Carcinogenic to Humans Reasonably anticipated to be human carcinogen
Legend	IARC - International Agency for Research on Cancer NTP - National Toxicology Program

Reproductive Toxicity No information available.





# Safety Data Sheet

PAGE 9 OF 11

SDS 0216/161

**Neurological Effects** No information available.

**STOT - single exposure** No information available. **STOT - repeated exposure** No information available.

Target organ(s)Liver, Central nervous system (CNS), Respiratory system, Kidney.

Aspiration Hazard No information available.

<u>Numerical measures of toxicity - Product Information</u> Unknown acute toxicity 60 - 70% of the mixture consists of ingredient(s) of unknown toxicity.

The following values are calculated based on chapter 3.1 of the GHS document .ATEmix (oral)2923 mg/kgATEmix (dermal)1967 mg/kgATEmix (inhalation-vapor)11.4 mg/L

### 12. ECOLOGICAL INFORMATION

#### **Ecotoxicity**

Styrene	
Log Kow	2.95
Bioconcentration factor (BCF)	74
Algae	EC50 = 1.4 mg/L (Pseudokirchneriella subcapitata) (72h)
-	EC50 0.46 - 4.3 mg/L (Pseudokirchneriella subcapitata) (72h)
	Fish LC50 3.24 - 4.99 mg/L (Pimephales promelas) (96 h) flow-through
	LC50 19.03 - 33.53 mg/L (Lepomis macrochirus) (96 h) static
	LC50 6.75 - 14.5 mg/L (Pimephales promelas) (96 h) static
	LC50 58.75 - 95.32 mg/L (Poecilia reticulata) (96 h) static
	Water Flea EC50 3.3 - 7.4 mg/L 48 h

#### Unknown aquatic toxicity

66.7% of the mixture consists of components(s) of unknown hazards to the aquatic environment.

#### Persistence/Degradability

No information available.

#### **Bioaccumulation**

No information available.

#### Other adverse effects

No information available.





# Safety Data Sheet

PAGE 10 OF 11

SDS 0216/161

### 13. DISPOSAL CONSIDERATIONS

#### Waste treatment methods

**Disposal Considerations** Hazardous waste. Can be incinerated, when in compliance with local regulations.

#### Contaminated packaging

Empty containers retain residue (liquid and/or vapour) and can be dangerous. DO NOT PRESSURIZE, CUT, WELD, BRAZE, SOLDER, DRILL, GRIND OR EXPOSE SUCH CONTAINERS TO HEAT, FLAME, SPARKS, STATIC ELECTRICITY, OR OTHER SOURCES OF IGNITION; THEY MAY EXPLODE AND CAUSE INJURY OR DEATH. Do not attempt to refill or clean container since residue is difficult to remove. Empty drums should be completely drained, properly bunged and promptly returned to a drum reconditioner. All containers should be disposed of in an environmentally safe manner and in accordance with governmental regulations.

### 14. TRANSPORT INFORMATION

NOT TO BE SENT BY MAIL	
TARIFF No.	3907
UN No.	1866
Substance IdentityNo. S.I.N. SANS 10232-3	1866
Emergency Action Code EAC SANS 10232-3	26
SANS10228:2006 S.I.N.	1866
SANS 10228:2006 Technical Name	Resin solution immiscible with water
SANS 10228:2006 Class	3
SANS 10228:2006 Danger Group	111
SANS10228:2006 SubsidiaryRisks	Nil
SANS 10228:2006 Packaging Methods SANS 10229	13.3
IMDG - SHIPPING NAME	Resin solution
IMDG - CODE	PAGE 3379
IMDG - CLASS	Class 3.3
IMDG - PACKAGING GROUP	111
IMDG - MARINE POLLUTANT	Yes
IMDG - EMS No.	<u>3-05</u>
IMDG - MFAGTABLE No.	310
IATA - SHIPPING NAME	Resin solution
IATA_CLASS	Class 3
IATA - SUBSIDIARY RISK(S)	None
IATA - PACKAGING GROUP	111
IATA - PACKAGINGINSTRUCTION Passenger	309
IATA - PACKAGING INSTRUCTION Cargo	310
TREMCARD No.	Notavailable





# Safety Data Sheet

PAGE 11 OF 11

SDS 0216/161

# 15. **REGULATORY INFORMATION**

EEC HAZARD CLASSIFICATION	Flammable. Harmful. Irritant. [R10; Xn; Xi] (Styrene)
<u>RISK PHRASES</u>	Flammable. Harmful by inhalation. Irritating to eyes and skin. [R: 10, 20,36/38]
SAFETY PHRASES	Do not breathe vapour. [S: 23]
NATIONAL LEGISLATION	South African Hazardous Substance Act 15 of 1973 South African Occupational Health & Safety Act (85 of 1993)

# 16. OTHER INFORMATION

NFPA Rating Health 2	Flammability 3	Instability 1
----------------------	----------------	---------------

Prepared By: M.Jagath & based on data from Reichhold Product Regulatory Department Phone Number: 031 713 0600 Revision Date: 12 February 2016

Disclaimer

This information is provided in good faith and is correct to the best of NCS Resins's knowledge as of the date hereof and is designed to assist our customers; however, NCS Resins makes no representation as to its completeness or accuracy. Our products are intended for sale to industrial and commercial customers. We require customers to inspect and test our products before use and to satisfy themselves as to suitability for their specific applications. Any use which NCS Resins customers or third parties make of this information, or any reliance on, or decisions made based upon it, are the responsibility of such customer or third party. NCS Resins disclaims responsibility for damages, or liability, of any kind resulting from the use of this information.

THERE ARE NO WARRANTIES OR REPRESENTATIONS, EXPRESS OR IMPLIED, INCLUDING THOSE OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE WITH RESPECT TO THIS INFORMATION OR TO THE PRODUCT IT DESCRIBES. IN NO EVENT SHALL NCS RESINS BE LIABLE FOR SPECIAL, INCIDENTAL, OR CONSEQUENTIAL DAMAGES.

End of Safety Data Sheet